Westhertzanon Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/20002BR-0153/1

Work Order Type: Weatherization

Audit Name: 2002BR-0153-Audit

CLIENT INFORMATION

Client Name: 20002BR-0153 Address:

Client ID: 20002BR-0153

Alt. Client ID: Bradley

CLIENT CONTACT INFORMATION

20002BR-0153 Applicant/Person of Record

AGENCY INFORMATION

Agency: Bradley-Cleveland Community Services Agency Agency Phone: (423) 479-4111

Address: 155 Sixth Street SE **Fax:** (423) 479-4113

Agency Contact: Birger, Perry Work Phone:

Cell Phone: (615) 566-4085

Email Address: birgerwood@aol.com

| Company Name & License Number: | |
|--------------------------------|--|
| | |

Contractor's Signature:

COMMENT

Duplex Site Built

Build Date approx: 1995

Certified Firm/Renovator required

Client Name: 20002BR-0153
Client ID: 20002BR-0153
Alt. Client ID: Bradley

Work Order (Bid Form)

Work Order Name: WO/20002BR-0153/1 Report Run On: 5/20/2010 DOE Weatherization Assistant

Version 8.5.0 Page 1 of 3

Measures

| Measure 1 Infiltration Redctn | | | | Components | | | | | Inspected | |
|-------------------------------|---------------------------|---|-------|------------|---------------------|-----------|-------|------------|-----------|--|
| C | | ersrtip DR-1(Front) & DR g room window with appr | | | at threshold | l of DR-1 | and W | / _ | | |
| | | | | | Estimated | | | Actual | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| 10 | Miscellaneous Supplies | Infiltration Reduction | Each | 1 | | | | | | |
| (| Other Detail | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | Measur | e Sub Total: | |] ; | Sub Total: | | |
| | | | | | | | | | | |
| | Measure 2 DW | H Tank Insulation | | | Componen Estimated | | | Actual | Inspected | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| 1 | Hot Water Equipment | DHW Tank Insulation | Each | 1 | | | | | | |
| 2 | Labor | DHW Tank Insulation | Each | 1 | | | | | | |
| (| Other Detail | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | | |
| | Field Notes: | | | | | | | | | |

| Measure 3 DW Comment | H Pipe Insulation | | | Componen | | | | Inspecte |
|---------------------------------|---|-------------|---------|------------------------|-------|-------|------------------|----------|
| # Material / Labor | Description / Comment | Units | | Estimated Unit Cost | Total | Otv | Actual Unit Cost | Total |
| | Description / Comment | | Qty | Unit Cost | ıotai | Qty | Unit Cost | TOTAL |
| 1 Insulation | DHW Pipe Insulation cost for 10' of wrap | Each | 1 | | | | | |
| 2. Labar | • | Гаар | 4 | | | | | |
| 2 Labor | DHW Pipe Insulation | Each | 1 | | | | | |
| Other Detail | | | | | | 1 | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measure | e Sub Total: | | , | Sub Total: | |
| Measure 4 Flo Comment 1120 S | or Ins. R-19 q Ft (no existing insulatio | n in crawls | | Component Estimated | | space | Actual | Inspecte |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | Floor Insulation - Fiberglass Batts - R-19 | SqFt | 1120 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measure | e Sub Total: | |] : | Sub Total: | |
| Field Notes: | | | | ı | | 1 | | |
| | | | | | | | | |

Report Run On: 5/20/2010